

From: [Jonathan Carroll](#)
To: [Moore, Gary](#)
Subject: Re: Tank 16 Patch bottom
Date: Tuesday, September 24, 2013 11:54:20 AM

No, and No.

From: "Moore, Gary" <Moore.Gary@epa.gov>
To: Jonathan Carroll <JCarroll@lazarusenergy.com>
Sent: Tuesday, September 24, 2013 11:53 AM
Subject: RE: Tank 16 Patch bottom

Jonathan:

Have you decided to replace the entire tank bottom? Did the report show that this was necessary?

Thanks

Gary Moore

Federal On-Scene Coordinator

U.S. EPA Region 6

214-789-1627 cell

214-665-6609 office

moore.gary@epa.gov

From: Jonathan Carroll <JCarroll@lazarusenergy.com>
Sent: Tuesday, September 24, 2013 11:37 AM
To: Moore, Gary
Cc: Steven Wilson
Subject: Fw: Tank 16 Patch bottom

What do you want us to do? see attached.

----- Forwarded Message -----

From: Andrew Martin <ajm@bbbtanksvc.com>
To: jcarroll@lazarusenergy.com
Cc: bobswain@bbbtanksvc.com; 'Jacob Swain' <jacobswain@bbbtanksvc.com>; garythompson@bbbtanksvc.com
Sent: Tuesday, September 24, 2013 7:50 AM
Subject: Tank 16 Patch bottom

Jonathan – Please see attached changes as well as comparisons per your request. I will call and follow up this morning with you accordingly. Thanks a for your time and consideration.

Andrew "Andy" J. Martin
Director
BBB Tank Services, Inc.
162 Independence Pkwy N



9568277

Baytown, Texas 77520

Office: 832.695-2132

Fax: 281.838-8748

Cell: 832.724.3149

ajm@bbbtanksvc.com

www.bbbtankservices.com